

COMPACT Splicing Connectors for All Conductor Types and Mounting Carrier for Ex Splicing Connectors; fo Ex eb Applications; 221 Series

Description and Installation




Strip conductor to 11 mm (0.43 inch).



Termination: Lift the lever to open the clamping unit and insert a stripped conductor.



Then, lower the lever to close the clamp.




Inserting a connector into the mounting carrier.



Removing a connector from the mounting carrier.



Removing a conductor.



Mounting type (440 V) Using spacers between the connectors.



Mounting type (440 V) Vertical mounting on DIN-35 rail



Mounting type (275 V) No spacers are used between the connectors.



Mounting type (440 V) Horizontal screw mounting on a flat surface



Mounting type (440 V) Mounting the carrier via non-conductive screws.



Mounting type (275 V) Mounting the carrier using conductive screws.